

M680403

MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS
BUREAU OF CONSTRUCTION CODES/BOILER DIVISION
P.O. BOX 30254, LANSING, MICHIGAN 48909
517-241-9334

CERTIFICATE OF BOILER INSPECTION

THE HEREIN DESCRIBED BOILER IS APPROVED FOR OPERATION AT A PRESSURE NOT TO EXCEED THE MAXIMUM OPERATING PRESSURE SPECIFIED HEREON, PROVIDED THE OWNER/USER HAS COMPLIED WITH ALL REQUIREMENTS OF 1965 PA 290, AS AMENDED AND THE RULES AND REGULATIONS PROMULGATED BY THE DIRECTOR OF THE DEPARTMENT. INSTALLATION, REINSTALLATION, ALTERATION, OR REPAIR OF THIS BOILER MUST BE IN STRICT CONFORMITY WITH THE REQUIREMENTS OF 1965 PA 290 AND THE BOILER RULES AND REGULATIONS. THE HOLDER OF THIS CERTIFICATE SHALL NOTIFY THE CHIEF INSPECTOR OF EVERY ACCIDENT INVOLVING PERSONAL INJURY OR DAMAGE TO THIS BOILER.

OWNER/USER

International Academy of Saginaw
Kevin Dobson
Business Manager
1944 Iowa Ave
Saginaw, MI 48601-5213

MANUFACTURER: AIC

STATE NO: MIR443756

BOILER TYPE: Fire Tube

NB# / MFG#: 226956

YEAR BUILT: 2016

DATE INSP: 01/19/2017

MAX OPR PRESS: 30

EXP DATE: 01/19/2020

SV PRESS: 30

INSPECTOR: Thomas Wagner

LOCATION

International Academy of Saginaw
1944 Iowa Ave
Saginaw, MI 48601-5213

Shelly Edgerton

DIRECTOR

David Stenrose

Chief, Boiler Division

BCC-300 (Rev. 1/14)

PLACE IN BOILER ROOM

M680402

MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS
BUREAU OF CONSTRUCTION CODES/BOILER DIVISION
P.O. BOX 30254, LANSING, MICHIGAN 48909
517-241-9334

CERTIFICATE OF BOILER INSPECTION

THE HEREIN DESCRIBED BOILER IS APPROVED FOR OPERATION AT A PRESSURE NOT TO EXCEED THE MAXIMUM OPERATING PRESSURE SPECIFIED HEREON, PROVIDED THE OWNER/USER HAS COMPLIED WITH ALL REQUIREMENTS OF 1965 PA 290, AS AMENDED AND THE RULES AND REGULATIONS PROMULGATED BY THE DIRECTOR OF THE DEPARTMENT. INSTALLATION, REINSTALLATION, ALTERATION, OR REPAIR OF THIS BOILER MUST BE IN STRICT CONFORMITY WITH THE REQUIREMENTS OF 1965 PA 290 AND THE BOILER RULES AND REGULATIONS. THE HOLDER OF THIS CERTIFICATE SHALL NOTIFY THE CHIEF INSPECTOR OF EVERY ACCIDENT INVOLVING PERSONAL INJURY OR DAMAGE TO THIS BOILER.

OWNER/USER

International Academy of Saginaw
Kevin Dobson
Business Manager
1944 Iowa Ave
Saginaw, MI 48601-5213

MANUFACTURER: Lochinvar

STATE NO: MIR417070

BOILER TYPE: Water Tube

NB# / MFG#: 00194214

YEAR BUILT: 2007

DATE INSP: 01/19/2017

MAX OPR PRESS: 30

EXP DATE: 01/19/2020

SV PRESS: 30

INSPECTOR: Thomas Wagner

LOCATION

International Academy of Saginaw
1944 Iowa Ave
Saginaw, MI 48601-5213

Shelly Edgerton

DIRECTOR

David Stenrose

Chief, Boiler Division

BCC-300 (Rev. 1/14)

PLACE IN BOILER ROOM

Shields Fire Protection
 5066 7 Mile Rd
 Bay City, MI 48706 US
 jb@shieldsfireprotection.com

Invoice

BILL TO
 Maya Guerra
 International Academy of Saginaw
 1944 Iowa Avenue
 Saginaw, MI 48601

SHIP TO
 Maya Guerra
 International Academy of Saginaw
 1944 Iowa Avenue
 Saginaw, MI 48601

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
31734	10/17/2019	\$271.00	11/16/2019	Net 30	

SALES REP
 Meaghan

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
10/17/2019	Annual Fire Extinguisher Service	Leak testing/parts inspection and chemical restoration	13	10.00	130.00
10/17/2019	Hydrostatic Testing/Recharge	12 year testing to ensure integrity of nitrogen compressed unit and rebuild to avoid buying a new unit	7	10.00	70.00
10/17/2019	Complete 6 Year Maintenance 10lb ABC	Complete rebuild of extinguisher in order to avoid buying new unit	1	10.00	10.00
10/17/2019	O-Ring	O-Ring, New	8	1.25	10.00
10/17/2019	Verification Collar	New Verification Collar indicating cylinder has been internally inspected	8	0.75	6.00
10/17/2019	Annual Emergency Light Inspection	Emergency lighting is tested annually to stay in compliance with NFPA code	1	0.00	0.00
10/17/2019	Battery-Emergency Fixture	Emergency Fixture Rechargeable Battery	2	22.50	45.00
10/17/2019	Reduced Visit Fee	Half off visit fee, sales, vip, local	1	0.00	0.00

REPORT FOR International Academy of Saginaw 1944 Iowa Ave. Saginaw, MI 48601 BELOW

BALANCE DUE

\$271.00

- All fire extinguishers/ 13 were serviced in compliance with NFPA 10 code
- All fire extinguishers/ 13 are mounted in compliance with NFPA 10 code
- All emergency lighting was tested in compliance with NFPA 10 code
- After 2 repairs, all emergency lighting is in compliance with NFPA 10 code
- Batteries under warranty for 3 years

